MATERIAL SAFETY DATA SHEET
This MSDS complies with OSHA'S Hazard Communication Standard 29 CFR 1910.1200 and OSHA Form 174

This widde compiles with our way and property of the control of th								
		UTOR'S INFORMATION						
			HMIS Rating: Health-1; Flammability-1; Reactivity-0; Personal Protection-B					
Manufactured For:	Lagasse Brothers, Inc.		DOT Hazard Classification: ORM-D					
Address:	1525 Kuebel Street	lder	Identity (trade name as used on label):					
Address:	New Orleans, LA 70123				eaner Bravo	2040		
Phone:	800-989-7487		OS Number: 142		Revision- 11			
			Information Calls: (770)422-2071					
			Date Prepared: 02/23/00 Prepared By: LF/CH					
SECTION 1 - MATERIAL IDENTIFICATION AND INFORMATION								
	AL NAMES AND COMMON NAMES		CAS Number	SARA	OSHA PEL	ACGIH	Carcinogen	
(Hazardous Components 1% or greater; Carcinogens 0.1% or greater)				III LIST	(ppm)	TLV (ppm)	Ref. Source **	
ISOBUTANE / PROPANE BLEND			75-28-5	No	800	800	d	
			74-98-6	No	1000	1000	d	
PETROLEUM SOLVENT			64742-54-7	No	5mg/m3	5mg/m3	d	
PETROLEUM DISTILLATE			8052-41-3	No	100	100	d	
SECTION 2 - PHYSICAL/CHEMICAL CHARACTERISTICS								
Boiling Point: N/A Specific Gravity (H2O=1): Concentrate Only = 0.908								
Vapor Pressure: PSIG @ 70°F (Aerosols): Max.60  Vapor Pressure (Non-Aerosols)(mm Hg and Temperature): N/A								
			vaporation Rate ( BuAc = 1): N/E					
Solubility in Water: Solul	ater Reactive: No							
	White foam with light lemon fragrance.							
SECTION 3 - FIRE AND EXPLOSION HAZARD DATA								
EL AMMARILITY as par					ability Limita	in Air by % i	n Volumo:	
FLAMMABILITY as per USA FLAME PROJECTION TEST  Auto Ignition Temperature  Flammability Limits in Air by % in Volume:  N/E  N/E  KLEL: N/E  W UEL: N/E								
FLASH POINT AND METHOD USED (non-aerosols): N/A EXTINGUISHER MEDIA: Foam, dry chemical, carbon dioxide, water.								
SPECIAL FIRE FIGHTING PROCEDURES: Self-contained breathing apparatus.								
Unusual Fire & Explosion Hazards: Do not expose aerosols to temperatures above 130°F or the container may rupture.								
SECTION 4 - REACTIVITY HAZARD DATA								
STABILITY [X] STABLE [] UNSTABLE   HAZARDOUS POLYMERIZATION [] WILL [X] WILL NOT OCCUR								
Incompatibility (Mat. to avoid): Strong oxidizers.  Conditions to Avoid: Open flame, welding arcs, heat.								
Hazardous Decomposition Products: CO, CO2.								
SECTION 5 - HEALTH HAZARD DATA								
PRIMARY ROUTES OF ENTRY: [X]INHALATION []INGESTION [X]SKIN ABSORPTION []EYE []NOT HAZARDOUS								
ACUTE EFFECTS:								
Inhalation: Excessive inhalation of vapors can be harmful and may cause headache, dizziness, asphyxia, anesthetic effects and possible unconsciousness.								
Eye Contact: Mild irritation.  Skin Contact: May aggravate existing skin conditions.								
Ingestion: Possible chemical pneumonitis if aspirated into lungs. Nausea.								
CHRONIC EFFECTS: (Effects due to excessive exposure to the raw materials of this mixture) May cause headaches, dizziness and nausea.								
Medical Conditions Generally Aggravated by Exposure: May aggravate existing eye, skin, or upper respiratory conditions.								
EMERGENCY FIRST AID PROCEDURES								
Eye Contact: Flush with water for 15 minutes. If irritated, seek medical attention.								
Skin Contact: Wash with soap and water. If irritated, seek medical attention.								
Inhalation: Remove to fresh air. Resuscitate if necessary. Get medical attention.								
Ingestion: DO NOT INDUCE VOMITING. Drink two large glasses of water. Get immediate medical attention.								
SECTION 6 - CONTROL AND PROTECTIVE MEASURES								
Respiratory Protection (specify type): If vapor concentration exceeds TLV, use respirator approved by NIOSH in a positive pressure mode.								
Protective Gloves: Latex if skin easily irritated.  Eye Protection: Safety glasses recommended.								
Ventilation Requirements: Adequate ventilation to keep vapor concentration below TLV.								
Other Protective Clothing & Equipment: None								
Hygienic Work Practices: Wash with soap and water before handling food. Remove contaminated clothing.								
Trygienic Work Fractices								
SECTION 7 - PRECAUTIONS FOR SAFE HANDLING AND USE  Stone To Be Taken If Material is Spilled Or Released. Absorb spilled liquid with suitable medium. Place in closed drum for proper disposal. Incingrate or								
Steps To Be Taken If Material Is Spilled Or Released: Absorb spilled liquid with suitable medium. Place in closed drum for proper disposal. Incinerate or landfill according to local, state or Federal regulations. DO NOT FLUSH LIQUID TO SEWER.								
Waste Disposal Methods: Aerosol cans when vented to atmospheric pressure through normal use, pose no disposal hazard.								
Precautions To Be Taken In Handling & Storage: Do not puncture or incinerate containers. Do not store at temperatures above 130°F.								
Other Precautions &/or Special Hazards: KEEP OUT OF REACH OF CHILDREN. Avoid food contamination. Avoid breathing vapors.								

We believe the statements, technical information and recommendations contained herein are reliable, but they are given without warranty or guarantee of any kind.

\*\* Chemical Listed as Carcinogen or Potential Carcinogen. [a] NTP [b] IARC Monograph [c] OSHA [d] Not Listed [e] Animal Data Only