

7020/7220/7420

8020


Material Safety Data Sheet

Identity		CORRECTABLE RIBBON CASSETTE		7020		FCC-004	
SECTION I							
Manufacturer's Name				Emergency Telephone Number			
Fuji Coplan Corporation				803-635-9799			
Address				Telephone Number for Information			
ROUTE 5-BOX 4175 Winnsboro, Fairfield Country, SOUTH CAROLINA 29180, USA				803-635-9799 or 516-543-0800			
				Date Prepared			
				JULY, 25, 1991			
SECTION II - Hazardous Ingredients/Identity Information							
Hazardous Components		CAS No.	OSHA PEL	ACGIH TLV	Other Limits		
Mineral oil (mist)		8012-95-1	5.0mg/m ³	5.0mg/m ³	N/A		
Carbon Black		1333-86-4	3.5mg/m ³	3.5mg/m ³	N/A		
Predominant Components				Not Applicable			
Coloring material							
Oil							
Resin							
Additive							
Polyethylene film							
SECTION III - Physical/Chemical Characteristics							
Melting point		N/A		Specific Gravity		N/A	
Boiling Point, Evaporation Rate		N/A		Vapor Pressure/Density		N/A	
Solubility in Water		No data available					
Appearance and Odor							
Polyethylene film coated on one side there of with black ink.							

SECTION IV - Fire and Explosion Hazard Data				
Flash Point	N/A		Flammable Limits	LEL N/A UEL N/A
Extinguishing Media	Water mist, Foam, Dry powder, CO ₂ gas, others			
Special Fire Fighting Procedures	N/A			
Unusual Fire and Explosion Hazards	None			
SECTION V - Reactivity Data				
Stability	Unstable		Condition to Avoid N/A	
	Stable	X		
Incompatibility (Material to Avoid)	None			
Hazardous Decomposition or Byproducts	None			
Hazardous Polymerization	May Occur		Condition to Avoid N/A	
	Will Not Occur	X		
SECTION VI - Health Hazard Data				
Route(s) of Entry:	Inhalation?	Skin?	Ingestion?	
	No	Yes	Yes	
Health Hazards (Acute and Chronic)	No data available			
Carcinogenicity:	NTP?	IARC Monographs?	OSHA Regulated?	
	No	No	No	
Signs and Symptoms of Exposure	No data available			
Medical Conditions	Generally Aggravated by Exposure			
	No data available			
Emergency and First Aid Procedures	Wash away with soap and water an ink sticking to skin. If ink has contacted eye, wash it with enough water, then consult a doctor.			

SECTION VI - Precautions for Safe Handling and Use			
Steps to Be Taken in Case Material is Released or Spilled			
An inadvertently released or rewound ribbon should be wound again on the reel.			
Waste Disposal Method			
No Special			
Precautions to Be Taken in Handling and Storing			
Should be stored at dark and cold place.			
Other Precautions			
None			
SECTION VII - Control Measures			
Respiratory Protection (Specify Type)			
None			
Ventilation	Local Exhaust	N/A	Special N/A
	Mechanical (General)	N/A	Other N/A
Protective Gloves		N/A	Eye Protection
			N/A
Other Protective Clothing or Equipment			
N/A			
Work/Hygienic Practices			
None			

FUJI COPIAN CORPORATION



Tim Scott, Q.A. Director
Fuji Copian Corporation